

## Overview

When sparse FDM parts are placed into a support removal tank, they can fill up with solution from the tank and water from the rinse. Most of this solution or water will drain from parts naturally within 30 minutes of their removal from the tank. However, in some cases, geometry will trap some liquid inside. Later, this liquid will slowly leach out. To avoid this, Stratasys recommends using a vacuum and/or oven to completely remove any liquid from your FDM parts. The best method is to use the vacuum first, followed by the oven. Either method can be effective individually if you increase the amount of time the part is in the oven or the number vacuum cycles applied to the part.

**Note: For some applications, it is critical that even solid parts have all of the moisture removed after being in the support removal tank. In these situations, use the steps in the oven-drying section of this document.**

## Process

**Rinse:** It's critical to rinse parts well after removing them from the support removal tank to ensure no residual support removal solution remains on the surface. Place each part under a stream of hot running water and use a sponge, brush or your hand to physically scrub the part while rinsing. (It may also be necessary to rinse parts again after the initial drain, vacuum chamber and oven.)

**Drain:** Once each part has been rinsed well, allow most of the liquid to drain away by gravity. For larger parts, this may take up to 30 minutes. Quickly rinse parts again under hot water to remove any remaining residue.

## Vacuum Chamber

### Step 1:

Prepare the vacuum by using a liner, shop towel or rag to absorb any liquid that will be pulled from within the parts. It can also be helpful to wrap each part in a shop towel or rag to absorb liquid as it is expelled.

### Step 2:

Place the parts in the vacuum chamber and pull a vacuum to around 30 torr (4 kPa).

**Note: If the part is not wrapped with a towel, you will see liquid and foam being pulled from the part.**

### Step 3:

Once the desired vacuum is reached, return the chamber to ambient pressure. Repeat this procedure two to three times to remove as much liquid as possible.

### Step 4:

Remove the parts from the vacuum chamber and rinse them again briefly under hot water. Wipe the parts down with a clean towel.



*Rinsing the part is critical to remove any surface residue.*



*Use a liner or shop towel to absorb any excess water in the vacuum chamber.*



*Use the vacuum chamber for multiple cycles to pull water out of the part.*

## Oven Drying

### Step 1:

Set oven to 70°C (158°F)

### Step 2:

Wrap each part in a shop towel or rag to absorb any moisture as it evaporates from the part.

### Step 3:

Place the parts in the oven. Leave smaller parts in for about an hour; larger parts require 1.5 to 2 hours.

### Step 4:

Remove parts from the oven and use a damp towel to wipe each part down, removing any residue.

## Check Your Work

After drying the parts completely, you can use an air compressor with a basic blow-gun tip to check for any remaining moisture. Simply blow air on the part at a close range and observe whether any moisture is expelled from any portion of it.



Set the oven to 70°C.



Wrap the part to absorb moisture and place it in the oven for 1 to 2 hours.

Stratasys | [www.stratasys.com](http://www.stratasys.com) | [info@stratasys.com](mailto:info@stratasys.com)

7665 Commerce Way  
Eden Prairie, MN 55344  
+1 888 480 3548 (US Toll Free)  
+1 952 937 3000 (Intl)  
+1 952 937 0070 (Fax)

2 Holtzman St.  
Science Park, PO Box 2496  
Rehovot 76124, Israel  
+972 74 745-4000  
+972 74 745-5000 (Fax)

### ISO 9001:2008 Certified

© 2009, 2014Stratasys Inc. All rights reserved. Stratasys, FDM and Fortus are registered trademarks and Fused Deposition Modeling, FDM Technology, Fortus 250mc, Fortus 360mc, Fortus 400mc, Fortus 900mc, Insight and Control Center are trademarks of Stratasys Inc., registered in the United States and other countries. ULTEM 9085 is a trademark of SABIC Innovative Plastics IP BV. All other trademarks are the property of their respective owners. Product specifications subject to change without notice. SSYS-BP-DryingSparseParts-03-14.

For more information about Stratasys systems, materials and applications, contact Stratasys Application Engineering at 1-855-693-0073 (toll free), +1 952-294-3888 (local/international) or [ApplicationSupport@Stratasys.com](mailto:ApplicationSupport@Stratasys.com).

